SUBSYSTEM :ELECT POWER DIST & CONT FMEA NO 05-6 -2329 -2 REV:05/03/88

ASSEMBLY : AFT PCA-1 & 2 :RBR56L15001BR P/N RI

The Carlotte of the Carlotte o

CRIT.FUNC: CRIT. HDW:

P/N VENDOR: QUANTITY : 4 VEHICLE 102 103 104

FOUR

COURSEN

1

EFFECTIVITY: Х  $_{\perp}X$ Х PHASE(S): PL LO X 00 DO LS

REDUNDANCY SCREEN: A-PASS B-FAIL C-PASS

PREPARED BY:

APPROVED BY (NASA):

DES R PHILLIPS HOVE REL М

APPROVED BY: REL William Cl About 5-6-68 QΕ 00. Courses 576/58

SSN 20. C. Stone 5/12/88 RELDO and STUDIES OF 574/50 QE /2/

### ITEM:

OΕ

RESISTOR, WIRE WOUND, 15K OHMS - ORB/SRB DC BUS POWER CONTROL

#### FUNCTION:

LIMITS CURRENT AS PART OF A VOLTAGE DIVIDER NETWORK FOR SENSING SRE DC BUS VOLTAGE FOR CONTROL OF SWITCHING REDUNDANT ORBITER POWER SOURCE TO SRB DC BUS: 54V76A131A1R45, R46; 55V76A132A1R44, R45

### FAILURE MODE:

SHORTS

#### CAUSE(S):

STRUCTURAL FAILURE, (MECHANICAL STRESS, VIBRATION), CONTAMINATION, THERMAL STRESS, ELECTRICAL STRESS, PROCESSING ANOMALY

## EFFECT(S) ON:

- (A) SUBSYSTEM (B) INTERPACES (C) MISSION (D) CREW/VEHICLE (E) FUNCTIONAL CRITICALITY EFFECT:
- (A) FIRST FAILURE NO EFFECT. LOSS OF VOLTAGE DIVIDER TO DETECT LOW VOLTAGE ON A SRB DC BUS.
- (B) INCORRECT SENSING (INDICATES HIGHER THAN ACTUAL \_VOLTAGE) OF ASSOCIATED SRB DC BUS VOLTAGE. LOSS OF REDUNDANCY FOR ONE OF TWO SRB DC BUSES IF PRIMARY POWER FEED FROM THE ORBITER TO THE AFFECTED SRB DC BUS FAILS TO A LOW VOLTAGE CONDITION.
- (C,D) FIRST FAILURE NO EFFECT. THIS CONDITION WILL NOT RESULT IN INADVERTENT SWITCHING OF SRB DC BUS TO ALTERNATE SOURCE OR LOSS OF ANY SRE DC BUS.

JBSYSTEM :ELECT POWER DIST & CONT FMEA NO 05-6 -2329 -2 REV:05/03/88

## FFECT(S) ON (CONTINUED):

- (A) SUBSYSTEM (B) INTERFACES (C) MISSION (D) CREW/VEHICLE (E) FUNCTIONAL CRITICALITY EFFECT:
- (E) POSSIBLE LOSS OF CREW/VEHICLE DUE TO LOSS OF TWO SRB DC BUSES DURING FIRST STAGE VIA THE FOLLOWING SCENARIO:
  - RESISTOR FAILS SHORTED.
  - (2) LOW VOLTAGE ON ASSOCIATED PRIMARY ORB/SRB DC BUS SOURCE RESULTING IN LOSS OF THAT SRB DC BUS DUE TO LOSS OF SWITCH OVER CAPABILITY CAUSED BY IMPROPER SENSING.
  - (3) LOSS OF SECOND DC BUS ON THE SAME SRB.

LOSS OF TWO SRB BUSES RESULTS IN LOSS OF THRUST VECTOR CONTROL FOR THE AFFECTED SRB AS WELL AS SRB RATE GYRO FLIGHT CONTROL DATA. FAILS "B" SCREEN BECAUSE IMPROPER SENSING WILL NOT BE MANIFESTED UNLESS THE ASSOCIATED PRIMARY SRB DC BUS FAILS.

## SPOSITION & RATIONALE:

- (A) DESIGN (B) TEST (C) INSPECTION (D) FAILURE HISTORY (E) OPERATIONAL USE:
- ., B, C, D) DISPOSITION AND RATIONALE:

#### .) DESIGN

E RER56 RESISTOR IS A 1/8 WATT FIXED RESISTOR WITH A WIRE WOUND EMENT. THE DEVICE IS AN "ACCURATE" (0.10% TOLERANCE) DEVICE WITH IAL LEADS CAPABLE OF FULL-LOAD OPERATION UP TO 125 °C AMBIENT MPERATURE AND DERATED LINEARLY TO ZERO LOAD AT 145 °C AMBIENT. THE SISTORS HAVE A FAILURE RATE OF .01% PER 1,000 HOURS. THIS FAILURE TE IS ESTABLISHED AT 50% CONFIDENCE ON THE BASIS OF LIFE TESTS ERMISSIBLE RESISTANCE CHANGE IS +/- 0.2% + 0.01 OHMS). THE PART IS ALIFIED TO MEET THE REQUIREMENTS OF MIL-R-39005/5. THE APPLICATION IS SO ANALYZED TO ASSURE COMPLIANCE WITH THE 50% DERATING CRITERIA OF THE BITER PROJECT PARTS LIST.

SUBSYSTEM : ELECT POWER DIST & CONT FMEA NO 05-6 -2329 -2 REV: 05/03/88

# (B) TEST

۵

THE FOLLOWING TESTS ARE PERFORMED ON A SAMPLE OF THE MANUFACTURER'S PRODUCT TO QUALIFY THE PRODUCT TO THE SPECIFICATION:

Mechanical stress d Ther Vibration e Proc b Contamination	stress d Thermal stress e Processing anomaly					
TEST / INSPECTION	a	b	c	đ	ė	
CONDITIONING DC RESISTANCE VISUAL AND MECHANICAL EXAMINATION SHORT-TIME OVERLOAD TEMPERATURE CYCLING SOLDERABILITY SALT WATER IMMERSION CYCLING DIELECTRIC WITHSTANDING VOLTAGE TERMINAL STRENGTH INSULATION RESISTANCE MOISTURE RESISTANCE RESISTANCE TO SOLDERING HEAT SHOCK VIBRATION RESISTANCE-TEMPERATURE CHARACTERISTIC LOW TEMPERATURE STORAGE LOW TEMPERATURE OPERATION LIFE FUNGUS RESISTANCE TO SOLVENTS HIGH TEMPERATURE EXPOSURE	x x x x x	X X X X X X X X X X X X X X X X X X X	x x x	x x x x	XXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXX	

QUALIFICATION TESTS

BSYSTEM :ELECT POWER DIST & CONT FMEA NO 05-6 -2329 -2 REV:05/03/88

للقروط فالمحاورة والخروان والمراوي والمحاور والمستنقط للقروص والمراوي والمستنط

# ) TEST (CONTINUED)

E FOLLOWING TESTS ARE PERFORMED ON A SAMPLE OF PARTS FROM EACH LOT TO MONSTRATE QUALIFICATION.

Mechanical stress d Vibration e b Contamination	chanical stress d Thermal stress ibration e Processing anomaly tamination CAUSE CONTROL					
TEST / INSPECTION		a	ь	¢	đ	8
VISUAL AND MECHANICAL INSPECTION SHORT-TIME OVERLOAD THERMAL SHOCK RESISTANCE-TEMPERATURE CHARACTERIST SOLDERABILITY INSULATION RESISTANCE MOISTURE RESISTANCE DIELECTRIC WITHSTANDING VOLTAGE TERMINAL STRENGTH RESISTANCE TO SOLVENTS	STIC	x	x x x x	x x	x x	* * * * * * * * * * * * * * * * * * *

# QUALIFICATION TESTS (LOT SAMPLE)

STS AND INSPECTIONS PERFORMED ON A PERIODIC BASIS AS A PART OF ALIFICATION ARE:

TEST / INSPECTION	CAUSE CONTROL						
		a	ъ	С	a	e	
LIFE			х	х	х	×	
LOW TEMPERATURE STORAGE		1			х	х	
LOW TEMPERATURE OPERATION .		1		l x	x	X	
RESISTANCE TO SOLVENTS		l x				X	
SALT WATER IMMERSION CYCLING		x		l		x	
DIELECTRIC WITHSTANDING VOLTAGE		1	X	x		Įχ	
FERMINAL STRENGTH		x		l		Ιx	
DC RESISTANCE		1	x	l		×	
VISUAL AND MECHANICAL INSPECTION		Ιx			'	מ	
SHORT-TIME OVERLOAD		1		lх		l x	
TEMPERATURE CYCLING		1	x	l	Х	X	
RESISTANCE TO SOLDERING HEAT	а	x		l	x	ג	
SHOCK		x		l		X	
VIBRATION .		x		l		ı x	
HIGH TEMPERATURE EXPOSURE			x	•	x	X	

QUALIFICATION TESTS (PERIODIC)

and the second s

SUBSYSTEM : ELECT POWER DIST & CONT FMEA NO 05-5 -2329 -2 REV: 05/06/88

### (B) TEST (CONTINUED)

CAUSES  a Structural failure  Mechanical stress  Vibration  b Contamination	uctural failure C El echanical stress d Th ibration e Pr				Electrical stress Thermal stress Processing anomaly CAUSE CONTROL						
TEST / INSPECTION	-		a	ъ	c	d	e				
POWER CONDITIONING DC RESISTANCE	<del></del> -			X			X X				

### QUALITY ASSURANCE TESTS (ALL DEVICES)

#### GROUND TURNAROUND TEST

NONE PERFORMED DUE TO RISK ASSOCIATED WITH REQUIRED TEST.

### (C) INSPECTION

THE PART HAS REQUIRED INSPECTION DURING MANUFACTURING PROCESS IN ACCORDANCE WITH THE REQUIREMENTS OF MIL-R-39005. IN ADDITION, THE PART SUPPLIER IS REQUIRED TO HAVE QUALITY AND PROCESS CONTROL PRACTICES IN ACCORDANCE WITH THE REQUIREMENTS OF MIL-R-39005 AND IN ADDITION, THE PART SUPPLIER IS REQUIRED TO HAVE A RELIABILITY PROGRAM IN ACCORDANCE WITH THE REQUIREMENTS OF MIL-STD-790. THE REQUIREMENTS ARE TO ASSURE ADEQUATE PROCESS CONTROLS ARE IMPOSED BY THE PART SUPPLIER ON THE PARTS MANUFACTURING PROCESS. THE PROCESSES AND CONTROLS ARE ROUTINELY REVIEWED AND APPROVED BY THE QUALIFYING AGENCY (DEFENSE ELECTRONIC SUPPLY CENTER).

#### RECEIVING INSPECTION (FAILURE CAUSE a,b,e)

INSPECTION OF INCOMING MATERIALS, UTILITIES AND IN-WORK PROCESSES (PACKAGES, WIRE, WATER PURIFICATION) IS REQUIRED OF THE PART SUPPLIER.

### CLEANLINESS CONTROL (FAILURE CAUSE b)

THE PART SUPPLIER IS REQUIRED TO HAVE CLEANLINESS AND ATMOSPHERE CONTROL IN CRITICAL WORK AREAS TO THE REQUIREMENTS OF FED-STD-209.

### ASSEMBLY/INSTALLATION (PAILURE CAUSE a,b,e)

THE PART SUPPLIER IS REQUIRED TO HAVE TRACEABILITY (DESCRIPTION OF PRODUCTION PROCESS AND CONTROLS, QUALITY CONTROL INSPECTION DOCUMENTATION, DATE OF SUBMISSION, INSPECTION CRITERIA, FINAL LOT DISPOSITION AND RECORDS RETENTION). THE MANUFACTURER IS ALSO REQUIRED TO SUBMIT A PROGRAM PLAN ESTABLISHING A MANUFACTURING FLOW CHART, A FUNCTIONAL ORGANIZATION CHART, INTERNAL AUDIT ACTIVITIES AND EXAMPLES OF DESIGN, MATERIAL EQUIPMENT STANDARDS AND PROCESS INSTRUCTIONS FOR APPROVAL BY THE QUALIFYING AGENCY.

UBSYSTEM : ELECT POWER DIST & CONT FMEA NO 05-6 -2329 -2 REV:05/03/88

C) INSPECTION (CONTINUED)

RITICAL PROCESSES (FAILURE CAUSE a.e)

HE PART SUPPLIER MUST HAVE REQUIREMENTS AND CONTROLS ON MATERIALS REPARATION; BONDING CRITERIA; REWORK CRITERIA; DESIGN, PROCESSING, ANUFACTURING, TESTING, AND INSPECTION DOCUMENTATION AND CHANGE CONTROL; ERSONNEL TRAINING; FAILURE/DEFECT ANALYSIS AND CORRECTIVE ACTION; AND NVENTORY CONTROL.

ESTING (FAILURE CAUSE a,b,c,d,e)

HE PART SUPPLIER MUST HAVE TEST EQUIPMENT MAINTENANCE AND CALIBRATION DITROLS WHICH COMPLY WITH THE REQUIREMENTS OF MIL-STD-45662 AND HAVE SEN APPROVED BY THE QUALIFYING AGENCY.

UNDLING/PACKAGING (FAILURE CAUSE a)

UNDLING PROCEDURES MUST PROVIDE PHYSICAL PROTECTION OF MATERIALS TRING ALL SEQUENCES OF PRODUCTION AND INSPECTION. ASSEMBLED PARTS ARE IYSICALLY PROTECTED DURING TESTING AND QUALITY CONFORMANCE INSPECTIONS. TORAGE OF PARTS IS IN A CONTROLLED AREA, REQUIRING AUTHORIZATION FOR EMOVAL FROM THE AREA AND PREPARATION FOR SHIPMENT.

### )) FAILURE HISTORY

ILURE MODE: SHORT, LOW RESISTANCE

R'S AB0824 AND AB0851
ENTIFIED NINE FAILURES OF DEFECTIVE RBR56 WIRE WOUND RESISTORS NUFACTURED BY ULTRONIX. THE FAILURE CAUSE WAS IDENTIFIED TO BE PROPER WINDING WHICH ALLOWED INTRA-WINDING SHORTS. THE IMPROPER CHNIQUE WAS CAUSED BY NOVICE OPERATORS WITH INADEQUATE SUPERVISION. CEPTANCE TESTING IS CONSIDERED TO BE AN EFFECTIVE SCREEN FOR THIS OBLEM.

) OPERATIONAL USE

NE